HOW TO DO A COMPLETE RESTART TO A TI525 or TI545 PLC

1. Hook up the following cable from the laptop computer com1 port to the RS232 program port on the TI525 or TI545 processor.
    500.1.1315 – TI525
    328.51.438 – TI545

2. Turn on the power to the laptop computer.

3. At the c:\> prompt, change the directory to the tisoft directory by typing CD\TISOFTx.
     (the tisoft directory name may change per application)

4. At the c:\TISOFTx> prompt type TI505 and then press the enter key.
     (you are now in the TISOFT programming software for the TI525 or TI545 PLC)

5. Go online with the PLC by pressing the F4-on line key.

6. When online with the PLC press the F6-aux key.(this is the screen that you will remain in for the remaining steps.)

7. To do a complete restart, use the arrow keys to move the cursor to the RESETS AND RESTARTS selection. To the right you will see various options. Type 12-Complete restart mode then press the enter key. When you receive the message, PLC complete restart?, press F2-yes.

8. When back to the auxiliary menu, exit the TISOFT program by pressing the F1-exit key, then the F2-yes key (when required) until you are back to the c:\> prompt on the computer. Disconnect the cable and turn off the laptop.