


## DTAM to Panelview 400+ (1747-DTAM)

If your DTAM (1747-DTAM) has faded to the point where it's difficult to read, keypad is worn out, or failed, then it's time to switch to the new **state-of-the-art Panelview 400+**. Not only does this latest screen emit an image that's **brighter** than your previous screen, makes **reading the entire screen easier**. What's more, converting to a Panelview 400+ is **quick and seamless** so you don't have to deal with costly down time while you upgrade your Panelview 400+.



Electrical number of machine and manufacture's part number of the PLC will be needed.

For more information on the benefits of Panelview 400+ conversion kit or safety features, please contact your local representative or call Columbia direct at (800) 628-4065.